

Fahrenheit to Kelvin Conversion Table

-460 to 500°F -- from absolute zero through everyday and industrial temps

$$K = (°F + 459.67) \times 5/9$$

°F	K
-460	-0.18
-450	5.37
-440	10.93
-430	16.48
-420	22.04
-410	27.59
-400	33.15
-390	38.71
-380	44.26
-370	49.82
-360	55.37
-350	60.93
-340	66.48
-330	72.04
-320	77.59
-310	83.15
-300	88.71
-290	94.26
-280	99.82
-270	105.37
-260	110.93
-250	116.48
-240	122.04
-230	127.59
-220	133.15

°F	K
-210	138.71
-200	144.26
-190	149.82
-180	155.37
-170	160.93
-160	166.48
-150	172.04
-140	177.59
-130	183.15
-120	188.71
-110	194.26
-100	199.82
-90	205.37
-80	210.93
-70	216.48
-60	222.04
-50	227.59
-40	233.15
-30	238.71
-20	244.26
-10	249.82
0	255.37
10	260.93
20	266.48
30	272.04

°F	K
40	277.59
50	283.15
60	288.71
70	294.26
80	299.82
90	305.37
100	310.93
110	316.48
120	322.04
130	327.59
140	333.15
150	338.71
160	344.26
170	349.82
180	355.37
190	360.93
200	366.48
210	372.04
220	377.59
230	383.15
240	388.71
250	394.26
260	399.82
270	405.37
280	410.93

°F	K
290	416.48
300	422.04
310	427.59
320	433.15
330	438.71
340	444.26
350	449.82
360	455.37
370	460.93
380	466.48
390	472.04
400	477.59
410	483.15
420	488.71
430	494.26
440	499.82
450	505.37
460	510.93
470	516.48
480	522.04
490	527.59
500	533.15