

Fahrenheit to Rankine Conversion Table

-40 to 500°F -- absolute temperature for imperial engineering

$$^{\circ}\text{Ra} = ^{\circ}\text{F} + 459.67$$

°F	°Ra	°F	°Ra	°F	°Ra	°F	°Ra	°F	°Ra
-40	419.67	80	539.67	200	659.67	320	779.67	440	899.67
-35	424.67	85	544.67	205	664.67	325	784.67	445	904.67
-30	429.67	90	549.67	210	669.67	330	789.67	450	909.67
-25	434.67	95	554.67	215	674.67	335	794.67	455	914.67
-20	439.67	100	559.67	220	679.67	340	799.67	460	919.67
-15	444.67	105	564.67	225	684.67	345	804.67	465	924.67
-10	449.67	110	569.67	230	689.67	350	809.67	470	929.67
-5	454.67	115	574.67	235	694.67	355	814.67	475	934.67
0	459.67	120	579.67	240	699.67	360	819.67	480	939.67
5	464.67	125	584.67	245	704.67	365	824.67	485	944.67
10	469.67	130	589.67	250	709.67	370	829.67	490	949.67
15	474.67	135	594.67	255	714.67	375	834.67	495	954.67
20	479.67	140	599.67	260	719.67	380	839.67	500	959.67
25	484.67	145	604.67	265	724.67	385	844.67		
30	489.67	150	609.67	270	729.67	390	849.67		
35	494.67	155	614.67	275	734.67	395	854.67		
40	499.67	160	619.67	280	739.67	400	859.67		
45	504.67	165	624.67	285	744.67	405	864.67		
50	509.67	170	629.67	290	749.67	410	869.67		
55	514.67	175	634.67	295	754.67	415	874.67		
60	519.67	180	639.67	300	759.67	420	879.67		
65	524.67	185	644.67	305	764.67	425	884.67		
70	529.67	190	649.67	310	769.67	430	889.67		
75	534.67	195	654.67	315	774.67	435	894.67		